

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/01/2019 5:17 PM

Date

Aug 1, 2019

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:45

Start Temperature

62

Start Cloud Cover

0

Start Wind Speed

0-2

End Time

14:55

End Temperature

92

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

1. Two excavators, one front loader, one blade, three water trucks, three sweepers, 60 bottom dump trucks. 2. 12 personnel (Griffith Company, Joe), 60 bottom dump truck personnel (various companies), 3 personnel (Cal Earth Transport).

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CASJ, YWAR, RLPA, ALHU, BLPH, CALT, SOSP, SBMU, CORA, ACWO, WTSW, MODO, Western fence lizard, CA ground squirrel, Coastal whiptail, common side-blotched lizard

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0705, monitored excavators and front loader loading dirt into bottom-dump trucks to be hauled off site. 0805, gave environmental training to one new LACDPW engineer. 0832, Updated MODO-1. 0850, Updated NRWS-3. 0856, Updated HOFI-3. 1120, gave environmental training to one new Griffith operator. 1157, Updated CATH-4. 1310, Updated CASJ-7. 1329, Updated CASJ-2. 1335, Updated BUSH-1.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read "B. M. J. L." or similar, written in a cursive style.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/16/2019 9:21 AM

Date

Aug 01, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

63

Start Cloud Cover

0

Start Wind Speed

0

End Time

15:30

End Temperature

87

End Cloud Cover

100

End Wind Speed

<5

Construction Activity and Personnel

irrigation construction, 8 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

scrub jay, California quail, common raven, cotton-tail, parrots, spotted towhee, deer

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A. Crew assembling irrigation

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

KWA WB

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/02/2019 5:12 PM

Date

Aug 2, 2019

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:50

Start Temperature

64

Start Cloud Cover

0

Start Wind Speed

0-2

End Time

14:45

End Temperature

94

End Cloud Cover

5

End Wind Speed

2-5

Construction Activity and Personnel

1. Two excavators, one front loader, one blade, three water trucks, three sweepers, 60 bottom dump trucks. 2. 12 personnel (Griffith Company, Joe), 60 bottom dump truck personnel (various companies), 3 personnel (Cal Earth Transport).

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CORA, YWAR, CATH, WEBL, BGGN, SOSP, COYE, CASJ, BLPH, HOFI, MODO, CLSW, NRWS, ACWO, Gopher, desert cottontail, common side-blotched lizard, western fence lizard

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0704, monitored excavators and front loader loading dirt into bottom-dump trucks to be hauled off site. 0840, Updated CASJ-3. 0849, Updated CATH-2.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Handwritten signature in black ink.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/09/2019 8:55 AM

Date

Aug 2, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Adam Schroeder

Start Time

07:00

Start Temperature

68

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

14:00

End Temperature

91

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to install irrigation tubing in DG-3A. Crew consisted of one foreman (Ron Crawford) and seven laborers.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CASJ WREN BEWR MODO NOMO RTHA AMCR ROPI LEGO HOFI ACWO NUWO ANHU CALT SPTO
desert cottontail, western fence lizard, California ground squirrel

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700, conducted pre-work sweep. 0715, crew began installing irrigation piping at DG-3A.
1400, biologist conducted final sweep and left for the day.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several stylized, connected loops and a long, sweeping tail that extends to the right.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/06/2019 6:36 AM

Date

Aug 5, 2019

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:45

Start Temperature

65

Start Cloud Cover

0

Start Wind Speed

0-2

End Time

15:00

End Temperature

95

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

1. Two excavators, one front loader, one blade, four water trucks, three sweepers, 60 bottom dump trucks. 2. 12 personnel (Griffith Company, Joe), 60 bottom dump truck personnel (various companies), 2 personnel (Cal Earth Transport).

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CALT, CAQU, MODO, RLPA, CASJ, CORA, BLPH, YRWA, YWAR, WTSW, NRWS, CLSW, ROPI, CA ground squirrel

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0707, monitored excavators and front loader loading dirt into bottom-dump trucks to be hauled off site.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/05/2019 4:16 PM

Date

Aug 5, 2019

Monitor Name

Brian Zitt

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Adam Schroeder

Start Time

06:25

Start Temperature

65

Start Cloud Cover

0

Start Wind Speed

1-2

End Time

13:30

End Temperature

90

End Cloud Cover

0

End Wind Speed

2-4

Construction Activity and Personnel

Nature's Image crew of eight, hand tools

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

Ca ground squirrel, American crow, green parrot, black phoebe, side-blotched lizard, scrub jay

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

Nature's Image crew installed irrigation plumbing in preparation for planting

Log Entry - Photos taken?

No

Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping loops and a long horizontal stroke extending to the right.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/06/2019 4:29 PM

Date

Aug 6, 2019

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:45

Start Temperature

67

Start Cloud Cover

50

Start Wind Speed

0-2

End Time

14:50

End Temperature

92

End Cloud Cover

10

End Wind Speed

1-3

Construction Activity and Personnel

1. Two excavators, one front loader, one blade, three water trucks, three sweepers, 60 bottom dump trucks. 2. 12 personnel (Griffith Company, Joe), 60 bottom dump truck personnel (various companies), 2 personnel (Cal Earth Transport).

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

BLPH, RLPA, ROPI, ANHU, CASJ, WTSW, HOFI, CORA, ACWO, CALT, BUSH, NOMO, Western fence lizard, CA ground squirrel

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0704- monitored excavators and front loader loading dirt into bottom-dump trucks to be hauled off site. 0840- Updated CLSW-1. 0842- Updated CLSW-2. 0844- Updated CLSW-3.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of a stylized first name followed by a last name, written in a cursive style.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/06/2019 4:44 PM

Date

Aug 6, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:55

Start Temperature

64

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

14:00

End Temperature

97

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Nature's Image (NI) crew of 8 installing irrigation on east side of project area.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CSJA, WREN, CALT, parrot sp., NUWO, ALHU, SPTO, BEWR, California ground squirrel, eastern fox squirrel, western side-blotch lizard, CAQU, SOSP, MODO, LEGO, HOFI, WEBL, ACWO, AMCR, CORA, EUST, BUSH, BGGN, BHGR, YEWA, ECDO, desert cottontail,

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700 NI foreman said plan for the day was to install irrigation in other restoration areas until container plants were delivered later in the week. One crrw member also checked and cleaned up pre-dug holes. 0900 Pasadena Water and Power crew using 2 backhoes on dirt access road north of staging area on east side and planned to conyinue until 3:00. 1330 NI crew started cleaning and packing up for the day. 1400 Biologist off site.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several stylized, overlapping loops and lines.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/07/2019 6:51 PM

Date

Aug 7, 2019

Monitor Name

Adam Schroeder

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:50

Start Temperature

63

Start Cloud Cover

50

Start Wind Speed

0-2

End Time

14:50

End Temperature

87

End Cloud Cover

35

End Wind Speed

1-3

Construction Activity and Personnel

1. Two excavators, one front loader, one blade, three water trucks, three sweepers, 60 bottom dump trucks. 2. 12 personnel (Griffith Company, Joe), 60 bottom dump truck personnel (various companies), 2 personnel (Cal Earth Transport).

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

RLPA, CALT, RSHA, CASJ, RTHA, TUVU, YRWA, ROPI, CA ground squirrel, western fence lizard

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0650, attended tailboard. 0704, monitored excavators and front loader loading dirt into bottom-dump trucks to be hauled off site.

Log Entry - Photos taken?

No

Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be "J. P. [unclear]", written in a cursive style.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/08/2019 8:12 AM

Date

Aug 7, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:30

Start Temperature

63

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

13:50

End Temperature

84

End Cloud Cover

15

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image (NI) crew of 8 installing irrigation for container plants in restoration areas on east side of project. Crew tested irrigation set up. Crew installed irrigation by hand and with hand tools. Crew also checked and made sure pre-dug holes for container plants to were ready for planting the following day.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

MODO, CALT, BUSH, WREN, SPTO, desert cottontail, bobcat, CAQU, parrot sp., BEWR, ALHU, LEGO, NUWO, AMCR, WEBL, HOOR, NOMO, ACWO, California ground squirrel, EUST, BUSH, ANHU, RTHA

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0630 Biologist onsite. Conducted sweep of work area. 0700 met NI crew. Foreman said plan for the day was to continue irrigation set up and test the system. The crew would make sure the site was prepared for planting the following day. 0823 Pasadena Water and Power crew using a backhoe to expose pipe under dirt access road on east side. (2nd photo) 1330 Crew wrapping

up for the day and are prepared for planting tomorrow. Biologist walked site while crew packed up. 1350 Biologist offsite.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping loops and a long horizontal stroke at the end.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/08/2019 2:58 PM

Date

Aug 8, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:45

Start Temperature

61

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

14:56

End Temperature

80

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Griffith co. 2 excavators, one front loader, one scraper, haul trucks

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CASJ, AMCR, BEWR, Parrot sp, CALT, LABU, HOFI, BUSH, SOSP, CLSW, ALHU, ROPI, RTHA, YWAR, LEGO, ANHU, WREN, SPTO, NUWO, CAQU, CATH, MODO, BTPI

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0645 arrived on site 0700 trucks began entering for sediment removal 0715-0815 swept perimeter for nests, no nests found 1500 crew finished for day, biologist left site

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several connected, somewhat abstract strokes. It appears to be a stylized name or set of initials.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/09/2019 9:13 AM

Date

Aug 8, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Lauren Simpson

Start Time

07:00

Start Temperature

67

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

14:00

End Temperature

88

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to install container plants at DG-3A. Species installed included 175 coast live oak and 115 California blackberry. Nature's Image crew consisted of one foreman (Ron Crawford) and seven laborers.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

BEWE BLPH CLSW NRWS AMCR RTHA LEGO HOFI EUST ROPI CALT SPTO CASJ ANHU MODO
NOMO ACWO

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700, conducted pre-work sweep. 0715, crew began unloading plants from delivery truck. Biologist inspected all plants for any signs of stress, damage, and or disease. 0730, crew began installing container plants. 1400, conducted final sweep.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be 'D. M.' followed by a long horizontal stroke.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/09/2019 2:52 PM

Date

Aug 9, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:45

Start Temperature

60

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:00

End Temperature

83

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Griffith co, 2 excavators, 1 front loader, 1 scraper, haul trucks

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

NUWO, CASJ, SBMU, YWAR, HOFI, CALT, parrot sp, cottontail, ca ground squirrel, ROPI, clsw, ANHU, ALHU, LABU, SPTO, LEGO, BEWR, OATI, CORA, BLPH, GREG, TUVU, whiptail, RSHA, HOOR

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0645 arrived on site conducted prework sweep 0710 trained new trucker 0715 checked project perimeter for active nests, none found 0700-1500 haul trucks removing sediment 1500 biologist left site. No bio issues observed

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several connected, wavy lines that form a stylized, cursive-like shape.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/09/2019 4:02 PM

Date

Aug 9, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Lauren Simpson

Start Time

07:00

Start Temperature

67

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

14:00

End Temperature

85

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to continue container plant installation at DG-3A. Crew consisted of one foreman (Ron Crawford) and seven laborers.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

AMCR, HOFI, LEGO, MODO, NOMO, BLPH, CLSW, NRWS, CALT, SPTO, CASJ, CATH, ANHU

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700, conducted pre-work sweep. 0715, crew began installing container plants at DG-3A.
1400, conducted final sweep.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of a large, stylized 'A' followed by several loops and a long horizontal stroke.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/13/2019 6:53 AM

Date

Aug 12, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

61

Start Cloud Cover

100

Start Wind Speed

0-1

End Time

15:30

End Temperature

88

End Cloud Cover

0

End Wind Speed

1-4

Construction Activity and Personnel

Griffith conducting sediment removal activities. Excavators loading haul trucks. Two excavators, 1 loader, two water trucks, 1 backhoe, and 1 blade. Two Griffith crew members directing truck traffic and three other crew members preparing trucks for demobilization off site with hose and brooms.

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CSJA, AMCR, CALT, BEWE, SOSP, ANHU, parrot sp., BEWR, SOSP, ANHU, YEWA, LEGO, western fence lizard, CLSW, ROPI, HOFI, OCWA, BLPH, RSHA, California ground squirrel, RSHA, CAQU, WREN,

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0610 Biologist onsite 0630 Met crew at staging area. Water trucks running 0650 Conducted WEAP training for new Griffith crew members. 0700 haul trucks arriving on site, crew began mobilizing, and sediment removal began. 0715 walked site 0915 conducted WEAP training to new driver 1300 only one excavator loading haul trucks. Other is down. 1417 Griffith foreman asked about expanding access roads within work area on west side. The plan was to clear and grade tomorrow if possible. I said I would sweep the area and adjacent areas today and tomorrow. 1418-1445 Surveyed area where Griffith planned to expand truck routes in work

area on west side. No sensitive biological resources detected within anticipated truck route. 1445 one backhoe and a crew with shovels worked to clean up scales and ramps to scales 1450 Last hail truck demobilized from site. Rest of crew preparing site for tomorrow and then crew demobilized. Biologist walked site. No biological concerns observed. 1530 biologist left

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/15/2019 6:54 AM

Date

Aug 12, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:17

Start Temperature

61

Start Cloud Cover

90

Start Wind Speed

0-1

End Time

13:30

End Temperature

86

End Cloud Cover

0

End Wind Speed

3-5

Construction Activity and Personnel

1) hand tools 2) Ron from Nature's Image

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CASJ, CORA, HOFI

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0615 - arrive on site survey area 0730 - WEEP training Nature's Image personnel 0745 - begin restoration monitoring at DG-2B 1030 - plant delivery

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B

TRIFLE LIFE NURSERY
A California Corporation
Sole To: Natures Image
20361 Hermans Circle
Lake Forest, CA 92630

CALIFORNIA NATIVE PLANTS

INVOICE No. 67568
P.O. Box 655
San Juan Capistrano, CA 92693
Phone (949) 728-0685 • Fax (949) 728-0509

Sale To: Natures Image
2877 N. Woodstar Ave
Altadena, CA 91001

Accession Number	Invoice Date	Date Shipped	F.O.B.	Comments	Page
NAT1MA	08/09/2019	08/09/19			1/1
Invoice Title No.	PO#2219				
203600	08/06/19				
Qty. Shipped	Qty. Invoiced	Item Name	Description	Net Price	ESTIMED PRICE
10	10	ARTE, CALI - 1G	Artemisa californica, - 01 Gal	3.80	38.00
10	10	BACC_PILU_CONDS/1G	Baccharis pilularis, - 01 Gal	3.80	38.00
20	20	BACC_SALI - 1G	Baccharis salicifolia, - 01 Gal	3.30	66.00
10	10	POPUL_FRM1 - 1G	Populus fremontii, - 01 Gal	4.20	42.00
10	10	RUBU_LRIS1 - 1G	Rubus leucostictus, - 01 Gal	5.35	53.50
10	10	ROSA_CALI - 1G	Rosa californica, - 01 Gal	4.55	45.50
10	10	SALL_GOOD - 1G	Salix goodenifolia, - 01 Gal	3.30	33.00
10	10	SALL_LAS1 - 1G	Salix lasiolepis, - 01 Gal	3.30	33.00
5	5	SAMB_MEX1 - 1G	Sambucus nigra ssp. caerulea, - 01 Gal	3.30	16.50
38	38	ARTE_CALI - 1G	Artemisa californica, - 01 Gal	3.80	144.40
38	38	BACC_PILU_CONDS/1G	Baccharis pilularis, - 01 Gal	3.80	144.40
38	38	BACC_SALI - 1G	Baccharis salicifolia, - 01 Gal	3.80	144.40
38	38	POPUL_FRM1 - 1G	Populus fremontii, - 01 Gal	4.20	159.60
38	38	RUBU_LRIS1 - 1G	Rubus leucostictus, - 01 Gal	5.35	203.30
38	38	ROSA_CALI - 1G	Rosa californica, - 01 Gal	4.55	172.90
70	70	SALL_GOOD - 1G	Salix goodenifolia, - 01 Gal	3.30	231.00
38	38	SALL_LAS1 - 1G	Salix lasiolepis, - 01 Gal	3.30	125.40
19	19	SAMB_MEX1 - 1G	Sambucus nigra ssp. caerulea, - 01 Gal	3.30	62.70
20	20	MELI_IMPE - 1G	Melica imperfecta, - 01 Gal	3.60	72.00
1	1	DEL_FEE	Delivery Fee	1.15	1.15
				Subtotal	2,355.40
				Labour	203.37
				Delivery	203.37
				Other	203.37
				TOTAL	2,978.77

TERMS OF SALE: This invoice is a contract for sale of goods and services. Payment is due at the time of shipment. Payment is due within 30 days of invoice date. If you do not agree to these terms, you must notify us within 30 days of invoice date. Payment in full is required for orders shipped outside California. Payment is due in full for orders shipped outside California.

RECEIVED AND ACCEPTED IN THE ABOVE TERMS BY: _____

Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/16/2019 6:30 AM

Date

Aug 13, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:12

Start Temperature

63

Start Cloud Cover

0

Start Wind Speed

0-2

End Time

15:30

End Temperature

91

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Griffith conducting sediment removal activities. 1 loader, 1 excavator, 2 water trucks, and 1 blade. Excavator and loader loading haul trucks while crew maintains and grades access roads. Some crew preparing trucks for demobilization off site.

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CALT, parrot sp., BEWR, AMCR, HUVI, YEWA, WREN, NUWO, SOSP, ALHU, LEGO, western fence lizard, HOFI, COYE, BLPH, MODO, OATI, CSJA, SPTO, ROPI, CLSW, WTSW ANHU, ACWO

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0612 onsite 0620 loader moving dirt on west side. Water trucks running 0630 met crew at staging area 0642 excavator mobilized. Biologist walked site 0700 haul trucks arriving. Surveyed area where crew planned on expanding access road. Surveyed west side and continued to walk site. 1150 Observed Griffith contain and clean up a minor spill. 1415 Conducted WEAP training

1437 Walked site 1450 Last haul trucks demobilized and crew preparing site for tomorrow.
1520 crew demobilized. Biologist conducted sweep of site. 1530 Biologist left site

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/14/2019 5:44 AM

Date

Aug 13, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Taylor Dee

Start Time

07:00

Start Temperature

69

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

14:00

End Temperature

89

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to install container plants at DG-2B. Plants were installed according to final HRP. Crew consisted of one foreman (Ron Crawford) and seven laborers.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CASJ, MODO, ANHU, NOMO, TUVU, RTHA, BLPH, CLSW, NRWS, HOFI, CALT, LEGO, AMCR, ROPI, EUST, BEWR, ACWO, CAQU

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700, conducted pre-work sweep. 0715, crew began installing plants in DG-2B. 1400, conducted final sweep.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of a large, stylized 'A' followed by a long horizontal stroke.

1

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/14/2019 3:12 PM

Date

Aug 14, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:50

Start Temperature

63

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:00

End Temperature

93

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Griffith Co. 2 excavators, 1 loader 1 scraper, haul trucks

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

Parrot sp., YWAR, ROPI, CORA, BUsh, hofi, clsw, CALT, ANHU, CASJ, SOSP, MODO, NOMO, LEGO, CA ground squirrel, BEWR, SPTO, AMCR, BTPI

Were Any Non-compliance Issues Observed?

Yes

Please State What Non-compliance Issues Occurred:

Biologist noted that the vegetation at the new tire wash station had been cleared and grubbed. Confirmed that biologists were not informed by the Contractor of the clearing activities and as a result no biologist had conducted a pre-clearing survey and no biologist was present to monitor during clearing. It is late in the nesting season and nesting activity on site is generally low, so it is unlikely that an active nest was present. The area that was cleared contained primarily disturbed CSS with CA sagebrush and CA buckwheat present but also high levels of nonnatives including Spanish broom and black mustard. Any wildlife affected would likely have been snakes, rodents, or lizards and with the warmer temperatures I would expect they would have been active enough to move out of harms way on their own during the removal.

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0650 biologist arrived on site. 0715 biologist provided WEAP training to 2 new LACPW workers
0730 biologist noted removed veg at tire wash station and began communication with LACPW
0730-1500 biologist surveyed site for presence of active nests or sensitive wildlife while hauling
operations occurred. No active nests located. Hauling complete at 1500, biologist left site

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Log Entry Photo D



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of a large, overlapping loop on the left side, followed by a series of smaller, connected loops and a final horizontal stroke on the right.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/20/2019 2:38 PM

Date

Aug 14, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Lauren Simpson

Start Time

07:00

Start Temperature

67

Start Cloud Cover

0

Start Wind Speed

1-3

End Time

13:30

End Temperature

91

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to install container plants and DG-2A and DG-2B and dig holes at DG-4C. Crew consisted of two foremen (Ron Crawford and Victor Aguirre) and 11 laborers.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CALT, SPTO, LEGO, HOFI, MODO, NOMO, AMCR,CAQU, CASJ, ACWO, EUST, CATH, CASJ, AMKE, desert cottontail, western fence lizard, California ground squirrel

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700, conducted pre-work sweep. 0715, crew began installing plants in DG-2A and DG-2B. 1100, conducted weekly sweep of oak trees in Oak Grove Park. No signs of root rot or other issues were observed; however, pooling was observed around one of the oak trees. The contractor was observed discussing options to fix the issue with the County. 1130, crew began digging holes for container plants in DG-4C. 1330,conducted final sweep.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke at the end.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/15/2019 6:22 PM

Date

Aug 15, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:32

Start Temperature

51

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:00

End Temperature

93

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Griffith Co. 2 excavators, 1 front loader, 1 scraper, 3 water trucks, haul trucks

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

HOOR, HOFI, CASJ, ALHU, CALT, parrot, SPTO, AMCR, CLSW, MODO, NUWO, YWAR, CORA

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0630 arrived on site, conducted pre work sweep 0700 haul trucks entered site 0715 provided WEAP training to 3 LACPW workers 0715-1500 conducted sweeps of project site, no issues observed 1500 biologist left site

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/16/2019 6:45 AM

Date

Aug 15, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

61

Start Cloud Cover

25

Start Wind Speed

0-1

End Time

13:30

End Temperature

95

End Cloud Cover

0

End Wind Speed

3-5

Construction Activity and Personnel

1) hand tools 2) Ron, Lalo, Victor, Manny from Nature's Image

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

MODO, CORA, HOFI, BEWR

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0615 - arrived onsite 0630 - installed ESA stakes 0715 - meet up with Natures Image crews
0720 - begin restoration monitoring DG-4C 1100 - receive plants for DG-3A 1145 - begin
planting at DG-3A 1330 - end restoration monitoring

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/23/2019 6:42 AM

Date

Aug 16, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

61

Start Cloud Cover

100

Start Wind Speed

0-1

End Time

15:01

End Temperature

90

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

1) two excavators, four water trucks, one grader, one loader 2) Joe from Griffith

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CORA, BEWR, BLPH, MODO, HOFI, side blotch lizard

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0645 - tailboard with Griffith 0700 - begin monitoring excavation activities 1500 - end excavation activities

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be the name "NADAN" written in a stylized, cursive font.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/19/2019 7:44 AM

Date

Aug 16, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:30

Start Temperature

61

Start Cloud Cover

100

Start Wind Speed

0-2

End Time

14:00

End Temperature

84

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Nature's Imagine crew conducted restoration activities on west side. Crew conducted nonnative weed abatement by hand and with hand tools, irrigation installation, and recieved irrigation pipe delivery. Container plants on east side were also irrigated. Crew also marked holes for container plnnts and proceeded to dig holes.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

MODO, AMCR, CALT, LEGO, CAQU, SOSP, SPTO, ANHU, CATH, EUST, BLPH, CSJA, parrot sp., BEWR, BUSH, WIFL, YEWA, BGGN, HOFI, NUWO, ALHU, desert cottontail, AMRO, OATI, California ground squirrel, western side-blotch lizard, western fence lizard, coastal whiptail,

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0630 onsite, conducted sweep of work areas. 0700 met NI crew on site. Foreman said plan of the day was to install irrigation and hand pull weeds. Crew began work. 0750 Foreman notified me that irrigation delivery was expected around 0800-0830 and crew would unload pipe the return to weed abatement and drip line installation. 0849 Irrigation pipe was delivered. Crew

unloaded before returning to week abatement and irrigation installation. 1100 portable bathrooms were delivered. 1315 Foreman said they planned to continue weeding and bagging removed vegetation while part of crew prepared holes for container plants. Plan for Monday was to start installing main irrigation pipe. 1317 walked site 1400 biologist left site. No impacts to sensitive biological resources observed.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping loops and strokes, positioned below the 'Signature' label.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/22/2019 7:50 AM

Date

Aug 19, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

61

Start Cloud Cover

100

Start Wind Speed

0-1

End Time

15:30

End Temperature

79

End Cloud Cover

0

End Wind Speed

1-2

Construction Activity and Personnel

Griffith conducted sediment removal activities. 2 excavators and 1 front loader loaded sediment into haul trucks. Laborers prepared trucks for demobilization offsite. 1 blade and 2 water trucks operating on access roads on site.

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CSJA, BEWR, parrot sp., SOSP, AMCR, desert cottontail, YEWA, LABU, ALHU, ANHU, HOFI, MODO, CORA, SBMU, CAQU, COHA, western fence lizard, CATH, LEGO, BLPH, NUWO

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0615 on site. 0630 met Griffith and Rest of crew at staging area. No vegetation clearing was planned for the day. 0632 conducted sweep of work areas 0700 Crew began construction activities and haul trucks began arriving on site. 0804 surveyed area before hand and then monitored removal of short emergent vegetation on work area. No wildlife or sensitive biological resources were detected before, during or after removal. Biologist monitored

sediment removal and associated activities: inspected testing holes for wildlife before loader backfilled them, walked site throughout the day to look for wildlife and other biological concerns. No impacts to sensitive biological resources were observed. 1500 Crew prepared to leave site. Biologist walked site. 1530 departed site

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several large, stylized, overlapping loops and strokes.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/29/2019 7:23 AM

Date

Aug 19, 2019

Monitor Name

Kent Hughesi

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

70

Start Cloud Cover

100

Start Wind Speed

0

End Time

15:30

End Temperature

88

End Cloud Cover

0

End Wind Speed

<5

Construction Activity and Personnel

Planting site preparation, 12 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

scrub jay, California quail, common raven, cotton-tail, parrots, California ground squirrel, common yellowthroat, California towhee

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A, B. Crew prepping planting site 5b.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read "Kurt Anderson". The signature is written in a cursive, flowing style with some loops and flourishes.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/20/2019 2:58 PM

Date

Aug 20, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:45

Start Temperature

64

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:00

End Temperature

88

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Griffith crew with 2 excavators 1 front loader 1 skip loader and 1 scraper, haul trucks. Filling haul trucks

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CASJ, SOSP, ANHU, AMCR, ALHU, HOFI, OATI, ROPI, ACWO, NUWO, SBMU, WTSW, YWAR, Parrot sp. MODO, Bush, Bcnh, CAQU, Cottontail, RTHA

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0645 arrived on site did pre work sweep 0715 trained one new LACPW worker 1000 monitored removal of emergent vegetation in small area 1100 trained 2 Tetra Tech workers 1500 left site. No bio issues observed

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several loops and a long, sweeping tail that extends to the right.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/21/2019 6:55 AM

Date

Aug 20, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

54

Start Cloud Cover

0

Start Wind Speed

0

End Time

15:30

End Temperature

92

End Cloud Cover

0

End Wind Speed

<5

Construction Activity and Personnel

irrigation construction, 8 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

scrub jay, California quail, common raven, cotton-tail, parrots, spotted towhee, California towhee

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A. Crew fusing irrigation mainline.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Kent Hartz

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/21/2019 2:52 PM

Date

Aug 21, 2019

Monitor Name

Lauren Simpson

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:46

Start Temperature

64

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:20

End Temperature

92

End Cloud Cover

0

End Wind Speed

0-1

Construction Activity and Personnel

Griffith crew with 2 excavators 1 front loader and 1 scraper. Loading haul trucks

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

BEWR, SOSP, CALT, hofi, clsw, parrot, AMCR, lego, ANHU, ALHU, SBMU, YWAR, BLPH, Cora, rtha

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0645 arrived on site conducted pre work sweep 0700 haul trucks began 0900 small amount of emergent vegetation removed near dam under biologist supervision 1500 biologist left site. No bio issues observed

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Log Entry Photo D



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several loops and a long horizontal stroke at the end.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/22/2019 9:07 AM

Date

Aug 21, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

54

Start Cloud Cover

0

Start Wind Speed

0

End Time

15:30

End Temperature

93

End Cloud Cover

0

End Wind Speed

<5

Construction Activity and Personnel

irrigation construction, 12 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

scrub jay, California quail, common raven, cotton-tail, parrots, Western blue bird, California towhee

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A. Crew fusing sections of irrigation main line.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read "K. A. R. 10".

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 09/04/2019 7:32 AM

Date

Aug 22, 2019

Monitor Name

Taylor Dee

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

70

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

13:15

End Temperature

88

End Cloud Cover

15

End Wind Speed

0-1

Construction Activity and Personnel

Sediment removal: 1 front loader, 2 excavators, 1 blade, and 2 water trucks. Loader and excavators loading haul trucks throughout the day. Five other crew members directing haul truck traffic and using a broom and hose to prep trucks for demobilization off site. Blade and loader conducted regular maintenance of access roads within sediment removal area.

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

Yes

Which species were observed?

Yellow warbler

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

BEWR, CALT, CSJA, parrot sp., WREN, RTHA, BUSH, ALHU, AMCR, HUVI, ANHU, BLPH, CAQU, ACWO, ROPI

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0615 arrived on site. 0630 met Griffith and Rest of crew at staging area. No vegetation clearing was planned for the day. 0736 Crew mobilized and began construction activities shortly after. 0700 Haul trucks began arriving on site. Sediment removal began. Biologist monitored sediment removal and associated activities: inspected testing holes for wildlife before loader backfilled them, walked site throughout the day to look for wildlife and other biological concerns. 1230 Haul trucks done for the day. Griffith crew preparing site for tomorrow. 1255 Confirmed with Griffith foreman that crew would be done by 1330 and crew would clean and tidy up site until then. Biologist walked site. 1315 Biologist left site. No impacts to sensitive biological resources were observed.

Log Entry - Photos taken?

Yes

Log Entry Photo A




Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several overlapping, fluid strokes that form an abstract, cursive shape. The signature is positioned below the word "Signature".

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/28/2019 12:19 PM

Date

Aug 22, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Taylor Dee

Start Time

07:00

Start Temperature

67

Start Cloud Cover

10

Start Wind Speed

1-3

End Time

14:00

End Temperature

89

End Cloud Cover

0

End Wind Speed

2-5

Construction Activity and Personnel

Nature's Image crew used hand tools to remove weeds and a mini excavator to dig holes for container plants in DG-5. Crew consisted of 2 foremans and 11 laborers.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CASJ, CAQU, HOFI, LEGO, TUVU, CALT, SPTO, ROPI, MODO, NOMO, RTHA, EUST, ACWO, CLSW, NRWS, BASW, BEWR, coyote, California ground squirrel, western fence lizard, western toad.

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700, conducted pre-work sweep. 0715, crew began removing weeds and digging holes in DG-5. 1400, crew done with removal and digging, conducted final sweep.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of a stylized, cursive script.

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/23/2019 9:19 PM

Date

Aug 23, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

62

Start Cloud Cover

100

Start Wind Speed

0-1

End Time

15:00

End Temperature

82

End Cloud Cover

0

End Wind Speed

3-5

Construction Activity and Personnel

1) two excavators, one loader, one grader, four water trucks 2) Joe and Johnny from Griffith

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CALT, CASJ, CORA, BEWR, BLPH, CAQU, CATH, ANHU, HOOR, OATI, HOWR, ACWO, western fence lizard, side-blotch lizard

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0615 - arrive on site 0700 - begin monitoring excavation activities 1500 - end excavation activities

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of several stylized, overlapping letters that appear to be 'NOM'.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/28/2019 1:01 PM

Date

Aug 23, 2019

Monitor Name

Carley Lancaster

Are Additional Monitors Present?

Yes

List Additional Monitors Present

Taylor Dee

Start Time

07:00

Start Temperature

65

Start Cloud Cover

10

Start Wind Speed

1-3

End Time

14:00

End Temperature

87

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

Nature's Image crew used hand tools to install irrigation and a mini dozers to dig holes for container plants at DG-4B. In addition, a tractor was used to rip soil at DG-5. Crew consisted of two foreman and 10 laborers.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

HOFI, MODO, LEGO, NOMO, AMCR, BEWR, CLSW, NRWS, CALT, SPTO, BUSH, WREN, ACWO, CAQU, ROPI, EUST, western toad, coyote, western fence lizard

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0700, conducted pre-work sweep. 0715, crew began installing irrigation and digging holes in DG-4B. 0900, crew began ripping soil in DG-5. 1400, conducted final sweep.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be the name 'A. W.' or similar, written in a cursive style.

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/26/2019 2:52 PM

Date

Aug 26, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

72

Start Cloud Cover

10

Start Wind Speed

0-1

End Time

08:30

End Temperature

73

End Cloud Cover

25

End Wind Speed

0-1

Construction Activity and Personnel

1) No construction activity 2) Joe from Griffith

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CORA, CALT, ROPI, MODO, BEWR, HOFI, BLPH, ACWO, COHA, HOWR,

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0615 - arrive on site 0630 - speak to Joe from Griffith, confirmation that all construction activities have been canceled due to near by fire. 0645- updating deactivated nests YWAR-2, CLSW-5, CLSW-6

Log Entry - Photos taken?

Yes

Log Entry Photo A




Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature



Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/28/2019 8:39 AM

Date

Aug 26, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

65

Start Cloud Cover

43

Start Wind Speed

0

End Time

15:30

End Temperature

94

End Cloud Cover

0

End Wind Speed

<5

Construction Activity and Personnel

Irrigation installation, site preparation for planting, 12 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

scrub jay, California quail, common raven, cotton-tail, parrots, California ground squirrel, common yellowthroat, California towhee

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A, B, C. Crew preparing area for planting.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Handwritten signature in black ink.

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/28/2019 6:40 AM

Date

Aug 27, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:15

Start Temperature

70

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:15

End Temperature

89

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

1) Two excavators, one grader, one loader, four water trucks 2) Joe from Griffith

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

CORA, HOWR, HOFI, BLPH, COHA, ACWO, CAJS, ANHU, BUSH, CALT, CATH, CAQU, RTHA, BEWR,

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0615 - arrive on site 0630 - coordinate with Joe from Griffith 0700 - begin excavation activities and monitoring 1515 - end monitoring excavation activities

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be the initials 'NSK' or similar, written in a stylized, cursive font.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/28/2019 8:00 AM

Date

Aug 27, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

67

Start Cloud Cover

47

Start Wind Speed

0

End Time

15:30

End Temperature

94

End Cloud Cover

0

End Wind Speed

<5

Construction Activity and Personnel

Irrigation installation, site preparation for planting, 12 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

scrub jay, California quail, common raven, cotton-tail, parrots, California ground squirrel, common yellowthroat, California towhee

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A, B, C. Crew installing plants.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

Kent K. S.

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/28/2019 8:55 PM

Date

Aug 28, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:30

Start Temperature

68

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:00

End Temperature

86

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

1) Two excavators, one loader, one grader, four water trucks 2) Joe and Johnny from Griffith

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

HOWR, HOFI, CORA, MODO, BLPH, RTHA, RSHA, ANHU, NUWO

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0630 - arrive on site 0700 - begun excavation monitoring 0845 - WEAP training 1500 - end excavation monitoring

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to be the letters 'NOM' with a stylized flourish.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/29/2019 7:17 AM

Date

Aug 28, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

70

Start Cloud Cover

100

Start Wind Speed

0

End Time

15:30

End Temperature

95

End Cloud Cover

0

End Wind Speed

<5

Construction Activity and Personnel

Plant installation, 12 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

scrub jay, California quail, common raven, cotton-tail, parrots, California ground squirrel, common yellowthroat, California towhee

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A, B. Crew installing plants.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read "Kurt M. [unclear]". The signature is written in a cursive style with a prominent initial "K" and a long horizontal stroke at the end.

Devil's Gate Biological Monitoring Log

Submitted By: DevilsGateGuest

Submitted Time: 08/29/2019 3:05 PM

Date

Aug 29, 2019

Monitor Name

Max Murray

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

06:30

Start Temperature

68

Start Cloud Cover

0

Start Wind Speed

0-1

End Time

15:04

End Temperature

91

End Cloud Cover

0

End Wind Speed

1-3

Construction Activity and Personnel

1) two excavators, one loader, one grader, four water trucks 2) Johnny from Griffith

What type of monitoring is being conducted?

Construction Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

ACWO, BLPH, CORA, HOFI, CASJ, RSHA, TUVU, HOWR, CALT,

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

0630 - arrive on site 0700 - begin monitoring excavation activities 1500 - end excavation monitoring

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Log Entry Photo C



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, consisting of stylized, overlapping letters.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 08/30/2019 7:42 AM

Date

Aug 29, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

68

Start Cloud Cover

0

Start Wind Speed

0

End Time

15:30

End Temperature

88

End Cloud Cover

0

End Wind Speed

<5

Construction Activity and Personnel

Installing plants, 12 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

No

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

California towhee, black phoebe, red shouldered hawk,

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A. Crew installing plants.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read "K. K. K." or similar, written in a cursive style.

Devil's Gate Biological Monitoring Log

Submitted By: SoCal_Bio

Submitted Time: 09/04/2019 9:15 AM

Date

Aug 30, 2019

Monitor Name

Kent Hughes

Are Additional Monitors Present?

No

List Additional Monitors Present

N/A

Start Time

07:00

Start Temperature

68

Start Cloud Cover

0

Start Wind Speed

0

End Time

15:30

End Temperature

87

End Cloud Cover

0

End Wind Speed

0

Construction Activity and Personnel

Installing plants, 12 people.

What type of monitoring is being conducted?

Restoration Monitoring

Covered Species Observed?

No

Which species were observed?

N/A

Were any least Bell's Vireo detected?

Yes

Include details of any least Bell's Vireo detected?

N/A

Other Wildlife Species Observed

California towhee, black phoebe, red shouldered hawk, parrots, California ground squirrel

Were Any Non-compliance Issues Observed?

No

Please State What Non-compliance Issues Occurred:

N/A

Did work activities occur outside predesignated work areas?

No

Include details of the work activities that occurred outside of the predesignated work areas.

N/A

Log Entry

A, B. Crew installing plants.

Log Entry - Photos taken?

Yes

Log Entry Photo A



Log Entry Photo B



Were ESA (Endangered Species Act) permits adhered to during the monitoring activities?

Yes

Log Completed?

Yes

Signature

A handwritten signature in black ink, appearing to read "Ken Smith". The signature is written in a cursive style with a large initial "K" and a stylized "S" at the end.